

SPP HPE Custom Image vibsdepot mapping for Pre-Gen9

HPE Custom Image to HPE SPP Mapping

Use the following links to view the table that maps the HPE Custom Images for the OS release to the vibsdepot directory and the supported HPE SPP release for Pre-Gen9 servers. The vibsdepot directory contains all the drivers and software added to the referenced HPE Custom Image, or the drivers and software for a hot-fix for the referenced HPE Custom Image as described in the footnotes. The HPE SPP contains the drivers included in the HPE Custom Image and the matching FW components.

Use the SPP link in the table to view detailed information on where to obtain the appropriate firmware, drivers and software for the supported OS releases and server generations for the SPP release. SPP documentation and downloads for all the SPP releases can be found at <http://www.hpe.com/servers/spp/download>. The SPP Component Release Notes contain a detailed list of all the firmware and driver components included in the SPP.

[VMware vSphere 6.7](#)

[VMware vSphere 6.5 U2](#)

[VMware vSphere 6.5 U1](#)

[VMware vSphere 6.5](#)

[VMware vSphere 6.0 U3](#)

[VMware vSphere 6.0 U2](#)

[VMware vSphere 6.0 U1](#)

[VMware vSphere 5.5 U3](#)

HPE SPP and HPE Software and Driver Mapping

Use the following links to view detailed information on where to obtain the appropriate firmware, drivers and software for the supported OS releases and server generations for the SPP release. None of the SPPs contain VMware components for HPE value-add software.

[2018.03.0](#)

[2017.10.1](#)

[2017.07.2](#)

[Gen8.1 Post Production SPP](#)

[G7.1 Post Production SPP](#)

[2017.04.0](#)

[2016.10.0](#)

[2016.04.0](#)

[2015.10.0](#)

The table in the Important Notes section in the VMware Software Recipe documents list all previously released HPE Custom Images that can be updated using the referenced HPE SPP and vibsdepot directory. For example, the entry below from the June 2017 VMware Software Recipe for the Service Pack for ProLiant (SPP) Version 2017.04.0 indicates that the HPE Custom Image for VMware vSphere 6.0 Update 2 (09 December 2016) can use the feb2017 vibsdepot directory to update the drivers and software to match the 2017.04.0 HPE SPP.

vSphere 6.0 Update 2	HPE Custom Image for VMware vSphere 6.0 Update 2(09 December 2016)	hpe-build-600.9.6.5.7-2494585
<p>Driver Updates are required Image does not contain driver versions specified in this Recipe Required drivers are available from: VUM online updates at: http://vibsdepot.hpe.com/hpe/preGen9/feb2017/index-driv.xml Offline bundles updated at: http://vibsdepot.hpe.com/hpe/preGen9/feb2017/esxi-600-devicedrivers (SPP) 2017.04.0 at: www.hpe.com/servers/spp/download Note: Both required driver and software updates are available from VUM online updates at: http://vibsdepot.hpe.com/hpe/preGen9/feb2017</p>		
<p>Software updates are required Image does not contain software versions specified in this Recipe Required software is available from: VUM online updates at: http://vibsdepot.hpe.com/hpe/preGen9/feb2017/index.xml Offline bundle updates at: http://vibsdepot.hpe.com/hpe/preGen9/feb2017/esxi-600-bundles Note: Both required driver and software updates are available from VUM online updates at: http://vibsdepot.hpe.com/hpe/preGen9/feb2017</p>		

VMware vSphere 6.7

No Pre-Gen9 Support

VMware vSphere 6.5 U2

The HPE Custom Image for VMware vSphere 6.5 U2 (3 May 2018) that supports pre-Gen9 servers is available on vmware.com at:
<https://my.vmware.com/web/vmware/details?downloadGroup=OEM-ESXI65U2-HPE&productId=614>

HPE Custom Image	HPE Custom Image Identifier	vibsdepot directory	HPE SPP	Comments
HPE Custom Image for VMware vSphere 6.5 U2 (28 May 2018)	oem-build-650.U2.9.6.7	http://vibsdepot.hpe.com/hpe/preGen9/may2018	Gen8.1 Post Production SPP ⁴ + 6.5 U2 Supplement	Includes updated nhpsa driver ⁵

⁴ SPP does not contain any VMware vSphere online FW or SW components for VMware vSphere 6.5 U2. FW update for servers running VMware vSphere 6.5 U2 must be done via offline FW update. Software update for servers running VMware vSphere 6.5 U2 must be done using the HPE Custom Image or vibsdepot. Driver updates for servers running VMware vSphere 6.5 U2 can be done using the HPE Custom Image, vibsdepot or the VMware vSphere 6.5 U2 Supplement for the Gen8.1 Post Production SPP.

⁵ This custom image and the 6.5 U2 Supplement includes an updated nhpsa driver. For details, refer to Customer Advisory https://support.hpe.com/hpsc/doc/public/display?docId=emr_na-a00043167en_us&docLocale=en_US

VMware vSphere 6.5 U1

The HPE Custom Image for VMware vSphere 6.5 U1 (30 Nov 2017) that supports pre-Gen9 servers is available on vmware.com at: <https://my.vmware.com/web/vmware/details?downloadGroup=OEM-ESXI65U1-HPE&productId=614>

HPE Custom Image	HPE Custom Image Identifier	vibsdepot directory	HPE SPP	Comments
HPE Custom Image for VMware vSphere 6.5 U1 (30 Nov 2017)	hpe-build-650.U1.9.6.5.1	http://vibsdepot.hpe.com/hpe/preGen9/nov2017	Gen8.1 Post Production SPP ⁴ + 6.5 U1 Supplement	

⁴ SPP does not contain any VMware vSphere online FW or SW components for VMware vSphere 6.5 U1. FW update for servers running VMware vSphere 6.5 U1 must be done via offline FW update. Software update for servers running VMware vSphere 6.5 U1 must be done using the HPE Custom Image or vibsdepot. Driver updates for servers running VMware vSphere 6.5 U1 can be done using the HPE Custom Image, vibsdepot or the VMware vSphere 6.5 U1 Supplement for the Gen8.1 Post Production SPP.

VMware vSphere 6.5

The HPE Custom Image for VMware vSphere 6.5 (08 May 2017) that supports pre-Gen9 servers is available on vmware.com at: <https://my.vmware.com/web/vmware/details?downloadGroup=OEM-ESXI65B-HPE&productId=614>

HPE Custom Image	HPE Custom Image Identifier	vibsdepot directory	HPE SPP	Comments
HPE Custom Image for VMware vSphere 6.5 (08 May 2017)	hpe-build-650.9.6.5.27	http://vibsdepot.hpe.com/hpe/preGen9/may2017	Gen8.1 Post Production SPP 2017.04.0 ⁴	6.5 Respin including VMware P01 Last Pre-Gen9 support
NA	NA	http://vibsdepot.hpe.com/hpe/preGen9/jan2017 ³	NA	6.5 OS Release hpilo driver HotFix
HPE Custom Image for VMware vSphere 6.5 (18 November 2016)	hpe-build-650.9.6.0.28	http://vibsdepot.hpe.com/hpe/preGen9/nov2016	2016.10.0 ⁴	6.5 GA OS Release

³ vibsdepot directory only contains 6.5 HPE value add software components with the hpilo driver HotFix. Should be used with previous 6.5 release

⁴ SPP does not contain any VMware vSphere online FW or SW components for VMware vSphere 6.5. FW update for servers running VMware vSphere 6.5 must be done via offline FW update. Software and driver update for servers running VMware vSphere 6.5 must be done using the HPE Custom Image or vibsdepot.

VMware vSphere 6.0 U3

The HPE Custom Image for VMware vSphere 6.0 Update 3 (23 February 2017) that supports Pre-Gen9 servers is available on vmware.com on the bottom of the page at: <https://my.vmware.com/web/vmware/details?downloadGroup=OEM-ESXI60U3-HPE&productId=491>

Gen8 servers

HPE Custom Image	HPE Custom Image Identifier	vibsdepot directory	HPE SPP	Comments
HPE Custom Image for VMware vSphere 6.0 Update 3 (23 February 2017)	hpe-build-600.9.7.0.17-2494585	http://vibsdepot.hpe.com/hpe/preGen9/feb2017	Gen8.1 Post Production SPP 2017.04.0 ⁴ 2016.10.0 ⁴	Gen8 6.0U3 OS Release Last Pre-Gen9 support

G7 and earlier servers

HPE Custom Image	HPE Custom Image Identifier	vibsdepot directory	HPE SPP	Comments
HPE Custom Image for VMware vSphere 6.0 Update 3 (23 February 2017)	hpe-build-600.9.7.0.17-2494585	http://vibsdepot.hpe.com/hpe/preGen9/feb2017	2017.04.0 ⁴ 2016.10.0 ⁴	G7 and earlier 6.0U3 OS Release Last Pre-Gen9 support

⁴ SPP does not contain any VMware vSphere online FW or SW components for VMware vSphere 6.0 U3. FW update for servers running VMware vSphere 6.0 U3 must be done via offline FW update. Software and driver update for servers running VMware vSphere 6.0 U3 must be done using the HPE Custom Image or vibsdepot.

VMware vSphere 6.0 U2

No Gen10 or newer support.

HPE Custom Image	HPE Custom Image Identifier	vibsdepot directory	HPE SPP	Comments
HPE Custom Image for VMware vSphere 6.0 Update 2 (09 December 2016)	hpe-build-600.9.6.5.7-2494585	http://vibsdepot.hpe.com/hpe/preGen9/dec2016	2016.10.0	Server/option updates
HP Custom Image for VMware vSphere 6.0 Update 2 (24 October 2016)	hpe-build-600.9.6.0.49-2494585	http://vibsdepot.hpe.com/hpe/preGen9/oct2016	2016.10.0	Server/option updates
HP Custom Image for VMware vSphere 6.0 Update 2 (01 April 2016)	hpe-build-600.9.5.0.48-2494585	http://vibsdepot.hpe.com/hpe/preGen9/apr2016	2016.04.0	Server/option updates
HP Custom Image for VMware vSphere 6.0 Update 2 (15 March 2016)	hpe-build-600.U2.9.4.7.13-2494585	http://vibsdepot.hpe.com/hpe/preGen9/mar2016	2015.10.0	6.0U2 OS Release

VMware vSphere 6.0 U1

No Gen10 or newer support.

HPE Custom Image	HPE Custom Image Identifier	vibsdepot directory	HPE SPP	Comments
HPE Custom Image for VMware vSphere 6.0 Update 1 (08 January 2016)	hpe-build-600.9.4.5.11-2494585	http://vibsdepot.hpe.com/hpe/preGen9/jan2016	2015.10.0	6.0U1b with Skylake Support

VMware vSphere 5.5 U3

No Gen10 or newer support.

HPE Custom Image	HPE Custom Image Identifier	vibsdepot directory	HPE SPP	Comments
NA	NA	http://vibsdepot.hpe.com/hpe/preGen9/apr2017 ¹	NA	5.5 HPE Utility Bundle Fix
HPE Custom Image for VMware vSphere 5.5 Update 3 (09 December 2016)	hp-build 550.9.6.5.9 -1198610	http://vibsdepot.hpe.com/hpe/preGen9/dec2016	2017.04.0 G7 Post Production SPP	Server/options updates
HP Custom Image for VMware vSphere 5.5 Update 3 (24 October 2016)	hp-build 550.9.6.0.45 -1198610	http://vibsdepot.hpe.com/hpe/preGen9/oct2016	2016.10.0	Server/option updates
HP Custom Image for VMware vSphere 5.5 Update 3 (01 April 2016)	hp-build 550.9.5.0.33 -1198610	http://vibsdepot.hpe.com/hpe/preGen9/apr2016	2016.04.0	Server/option updates
HP Custom Image for VMware vSphere 5.5 Update 3 (08 December 2015)	hp-build 550.9.4.5.7 -1198610	http://vibsdepot.hpe.com/hpe/preGen9/dec2015	2015.10.0	5.5U3b with Skylake Support

¹ vibsdepot directory only contains 5.5 HPE value add software components with the utility bundle fix. Should be used with previous 5.5 release.

2018.03.0 SPP

2017.10.1 SPP

2017.07.2 SPP

No pre-Gen9 support

Gen8.1 Post Production

Pre-Gen9 servers are only supported in the Post Production SPP.

VMware vSphere 6.5 U2 Supplement for the Gen8.1 Post Production SPP supports driver update for 6.5 U2.

VMware vSphere 6.5 U1 Supplement for the Gen8.1 Post Production SPP supports driver update for 6.5 U1.

G7 servers are not supported with 6.5 or updates or with the Gen8.1 Post Production SPP.

Gen8.1 Post Production SPP does not contain any VMware vSphere online FW or SW components for VMware vSphere 6.5, 6.5 U1 or 6.5 U2, but the supplements for VMware vSphere 6.5 U1 and 6.5 U2 do contain online driver components.

- FW update for servers running VMware vSphere 6.5, 6.5 U1 and 6.5 U2 must be done via offline FW update.
- Software and driver updates for servers running VMware vSphere 6.5 must be done using the HPE Custom Image or vibsdepot.
- Software updates for servers running VMware vSphere 6.5 U1 and 6.5 U2 must be done using the HPE Custom Image or vibsdepot.
- Driver updates for servers running VMware vSphere 6.5 U1 can be done using the HPE Custom Image, vibsdepot or the VMware vSphere 6.5 U1 Supplement for the Gen8.1 Post Production SPP.
- Driver updates for servers running VMware vSphere 6.5 U2 can be done using the HPE Custom Image, vibsdepot or the VMware vSphere 6.5 U2 Supplement for the Gen8.1 Post Production SPP.

SPP documentation and downloads for the Gen8.1 SPP release can be found at <http://www.hpe.com/servers/spp/download?version=Gen8.1>

vSphere version	Firmware	Drivers	Software
6.5 U2	Gen8.1 Post Production SPP Offline FW update	<ul style="list-style-type: none"> • HPE Custom Image for VMware vSphere 6.5 U2 (28 May 2018) • vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/may2018 • VMware vSphere 6.5 U2 Supplement for the Gen8.1 Post Production SPP Online Update 	<ul style="list-style-type: none"> • HPE Custom Image for VMware vSphere 6.5 U2 (28 May 2018) • vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/may2018
6.5 U1	Gen8.1 Post Production SPP Offline FW update	<ul style="list-style-type: none"> • HPE Custom Image for VMware vSphere 6.5 U1 (30 Nov 2017) • vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/nov2017 • VMware vSphere 6.5 U1 Supplement for the Gen8.1 Post Production SPP Online Update 	<ul style="list-style-type: none"> • HPE Custom Image for VMware vSphere 6.5 U1 (30 Nov 2017) • vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/nov2017
6.5	Gen8.1 Post Production SPP Offline FW update	<ul style="list-style-type: none"> • HPE Custom Image for VMware vSphere 6.5 (08 May 2017) • vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/may2017 	<ul style="list-style-type: none"> • HPE Custom Image for VMware vSphere 6.5 (08 May 2017) • vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/may2017
6.0 U3	Gen8.1 Post Production SPP Online or Offline FW update	<ul style="list-style-type: none"> • HPE Custom Image for VMware vSphere 6.0 Update 3 (23 February 2017) • vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/feb2017 • Gen8.1 Post Production SPP Online Update 	<ul style="list-style-type: none"> • HPE Custom Image for VMware vSphere 6.0 Update 3 (23 February 2017) • vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/feb2017

G7.1 Post Production

First G7 Post Production SPP.

Pre-Gen9 servers are only supported in the Post Production SPP.

G7 servers are not supported on VMware vSphere 6.5 and updates.

G7 Post Production SPP does not support VMware vSphere 6.5 U1, 6.5 or 6.0 U3

SPP documentation and downloads for the G7.1 Post Production SPP release can be found at <http://www.hpe.com/servers/spp/download?version=G7.1>

vSphere version	Firmware	Drivers	Software
5.5 U3	G7.1 Post Production SPP Online or Offline FW update	<ul style="list-style-type: none"> • HPE Custom Image for VMware vSphere 5.5 Update 3 (09 December 2016) + http://vibsdepot.hpe.com/hpe/preGen9/apr2017 • vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/dec2016 + http://vibsdepot.hpe.com/hpe/preGen9/apr2017 • G7.1 Post Production SPP online update 	<ul style="list-style-type: none"> • HPE Custom Image for VMware vSphere 5.5 Update 3 (09 December 2016) + http://vibsdepot.hpe.com/hpe/preGen9/apr2017 • vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/dec2016 + http://vibsdepot.hpe.com/hpe/preGen9/apr2017

2017.04.0 SPP

2017.04.0 SPP does not contain any VMware vSphere online FW or SW components for VMware vSphere 6.0 U3, 6.5 or 6.5 U1. FW update for servers running VMware vSphere 6.0 U3, 6.5 and 6.5 U1 must be done via offline FW update. Software and driver update for servers running VMware vSphere 6.0 U3, 6.5 and 6.5 U1 must be done using the HPE Custom Image or vibsdepot.

Last SPP to support 5.5 U3.

Last full SPP to support Pre-Gen9 servers.

SPP documentation and downloads for the 2017.04.0 SPP release can be found at <http://www.hpe.com/servers/spp/download?version=2017.04.0>

vSphere version	Firmware	Drivers	Software
6.5 U1	2017.04.0 SPP Offline FW update	<ul style="list-style-type: none"> HPE Custom Image for VMware vSphere 6.5 U1 (30 Nov 2017) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/may2017 	<ul style="list-style-type: none"> HPE Custom Image for VMware vSphere 6.5 U1 (30 Nov 2017) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/may2017
6.5	2017.04.0 SPP Offline FW update	<ul style="list-style-type: none"> HPE Custom Image for VMware vSphere 6.5 (08 May 2017) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/may2017 	<ul style="list-style-type: none"> HPE Custom Image for VMware vSphere 6.5 (08 May 2017) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/may2017
6.0 U3	2017.04.0 SPP Offline FW update	<ul style="list-style-type: none"> HPE Custom Image for VMware vSphere 6.0 Update 3 (23 February 2017) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/feb2017 	<ul style="list-style-type: none"> HPE Custom Image for VMware vSphere 6.0 Update 3 (23 February 2017) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/feb2017
5.5 U3	2017.04.0 SPP Online or Offline FW update	<ul style="list-style-type: none"> HPE Custom Image for VMware vSphere 5.5 Update 3 (09 December 2016) + http://vibsdepot.hpe.com/hpe/preGen9/apr2017 vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/dec2016 + http://vibsdepot.hpe.com/hpe/preGen9/apr2017 2017.04.0 SPP Online update 	<ul style="list-style-type: none"> HPE Custom Image for VMware vSphere 5.5 Update 3 (09 December 2016) + http://vibsdepot.hpe.com/hpe/preGen9/apr2017 vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/dec2016 + http://vibsdepot.hpe.com/hpe/preGen9/apr2017

2016.10.0 SPP

2016.10.0 SPP does not contain any VMware vSphere online FW or SW components for VMware vSphere 6.0 U3 or 6.5. FW update for servers running VMware vSphere 6.0 U3 and 6.5 must be done via offline FW update. Software and driver update for servers running VMware vSphere 6.0 U3 and 6.5 must be done using the HPE Custom Image or vibsdepot.

First SPP to support 6.5 and 6.0 U3. Last SPP to support 6.0 U2. SPP documentation and downloads for the 2016.10.0 SPP release can be found at https://support.hpe.com/hpsc/swd/public/detail?swItemId=MTX_3c2bfc8c3b446a7a9451c4ab9

vSphere version	Firmware	Drivers	Software
6.5	2016.10.0 SPP Offline FW update	<ul style="list-style-type: none"> HPE Custom Image for VMware vSphere 6.5 (18 November 2016) + http://vibsdepot.hpe.com/hpe/preGen9/jan2017 vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/nov2016 + http://vibsdepot.hpe.com/hpe/preGen9/jan2017 	<ul style="list-style-type: none"> HPE Custom Image for VMware vSphere 6.5 (18 November 2016) + http://vibsdepot.hpe.com/hpe/preGen9/jan2017 vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/nov2016 + http://vibsdepot.hpe.com/hpe/preGen9/jan2017
6.0 U3	2016.10.0 SPP Offline FW update	<ul style="list-style-type: none"> HPE Custom Image for VMware vSphere 6.0 Update 3 (23 February 2017) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/feb2017 	<ul style="list-style-type: none"> HPE Custom Image for VMware vSphere 6.0 Update 3 (23 February 2017) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/feb2017
6.0 U2	2016.10.0 SPP Online or Offline FW update	<ul style="list-style-type: none"> HPE Custom Image for VMware vSphere 6.0 Update 2 (09 December 2016) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/dec2016 2016.10.0 SPP Online update 	<ul style="list-style-type: none"> HPE Custom Image for VMware vSphere 6.0 Update 2 (09 December 2016) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/dec2016
6.0 U2	2016.10.0 SPP Online or Offline FW update	<ul style="list-style-type: none"> HP Custom Image for VMware vSphere 6.0 Update 2 (24 October 2016) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/oct2016 2016.10.0 SPP Online update 	<ul style="list-style-type: none"> HP Custom Image for VMware vSphere 6.0 Update 2 (24 October 2016) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/oct2016
5.5 U3	2016.10.0 SPP Online or Offline FW update	<ul style="list-style-type: none"> HPE Custom Image for VMware vSphere 5.5 Update 3 (09 December 2016) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/dec2016 2016.10.0 SPP Online update 	<ul style="list-style-type: none"> HPE Custom Image for VMware vSphere 5.5 Update 3 (09 December 2016) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/dec2016
5.5 U3	2016.10.0 SPP Online or Offline FW update	<ul style="list-style-type: none"> HP Custom Image for VMware vSphere 5.5 Update 3 (24 October 2016) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/oct2016 2016.10.0 SPP Online update 	<ul style="list-style-type: none"> HPE Custom Image for VMware vSphere 5.5 Update 3 (24 October 2016) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/oct2016

2016.04.0 SPP

Last SPP to support 5.1 U3

SPP documentation and downloads for the 2016.04.0 SPP release can be found at

https://support.hpe.com/hpsc/swd/public/detail?swItemId=MTX_d32057eee2bc45f187b3c3fbcf

vSphere version	Firmware	Drivers	Software
6.0 U2	2016.04.0 SPP Online or Offline FW update	<ul style="list-style-type: none"> HP Custom Image for VMware vSphere 6.0 Update 2 (01 April 2016) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/apr2016 2016.04.0 SPP Online update 	<ul style="list-style-type: none"> HP Custom Image for VMware vSphere 6.0 Update 2 (01 April 2016) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/apr2016
5.5 U3	2016.04.0 SPP Online or Offline FW update	<ul style="list-style-type: none"> HP Custom Image for VMware vSphere 5.5 Update 3 (01 April 2016) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/apr2016 2016.04.0 SPP Online update 	<ul style="list-style-type: none"> HP Custom Image for VMware vSphere 5.5 Update 3 (01 April 2016) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/apr2016
5.1 U3	2016.04.0 SPP Online or Offline FW update	<ul style="list-style-type: none"> HP Custom Image for VMware ESXi 5.1.0 Update 3 (01 April 2016) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/apr2016 2016.04.0 SPP Online update 	<ul style="list-style-type: none"> HP Custom Image for VMware ESXi 5.1.0 Update 3 (01 April 2016) vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/apr2016

2015.10.0 SPP

SPP documentation and downloads for the 2016.04.0 SPP release can be found at

https://support.hpe.com/hpsc/swd/public/detail?swItemId=MTX_1d06af9e8a0a4e43b8981b4471

vSphere version	Firmware	Drivers	Software
6.0 U2	2015.10.0 SPP Online or Offline FW update	<ul style="list-style-type: none">• HP Custom Image for VMware vSphere 6.0 Update 2 (15 March 2016)• vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/mar2016• 2015.10.0 SPP Online update	<ul style="list-style-type: none">• HP Custom Image for VMware vSphere 6.0 Update 2 (15 March 2016)• vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/mar2016
6.0 U1	2015.10.0 SPP Online or Offline FW update	<ul style="list-style-type: none">• HPE Custom Image for VMware vSphere 6.0 Update 1 (08 January 2016)• 2015.10.0 SPP Online update	<ul style="list-style-type: none">• HPE Custom Image for VMware vSphere 6.0 Update 1 (08 January 2016)
5.5 U3	2015.10.0 SPP Online or Offline FW update	<ul style="list-style-type: none">• HP Custom Image for VMware vSphere 5.5 Update 3 (08 December 2015)• vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/dec2015• 2015.10.0 SPP Online update	<ul style="list-style-type: none">• HP Custom Image for VMware vSphere 5.5 Update 3 (08 December 2015)• vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/dec2015
5.1 U3	2015.10.0 SPP Online or Offline FW update	<ul style="list-style-type: none">• HP Custom Image for VMware ESXi 5.1.0 Update 3 (09 November 2015)• vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/nov2015• 2015.10.0 SPP Online update	<ul style="list-style-type: none">• HP Custom Image for VMware ESXi 5.1.0 Update 3 (09 November 2015)• vibsdepot at http://vibsdepot.hpe.com/hpe/preGen9/nov2015

Revision History

Date	Version	Change Description
05.28.2018	1.6	Update version and date for 6.5 U2 release
05.03.2018	1.5	Added VMware vSphere 6.5 U2 release Update vibsdepot URLs to new preGen9 URLs
04.17.2018	1.4	Added VMware vSphere 6.7 Added links to SPP downloads and documentation Remove Gen8.0 Post Production SPP, replace by Gen8.1
02.05.2018	1.3	Added 2017.10.1 and 2018.03.0 SPP as no support for pre-Gen9 servers.
11.30.2017	1.2	Added VMware vSphere 6.5 U1 Supplement for Gen8.1 Post Production SPP Fix 5.5 U3 table to list 2017.04.0 SPP as supported with December HPE Custom Image Correct G7 Post Production SPP table and add the G7 Post Production SPP to the 5.5 U3 table
10.26.2017	1.1	Added all Post Production SPP releases
10.06.2017	1.0	Initial version

Get connected

hpe.com/info/getconnected

Current HPE driver, support, and security alerts
delivered directly to your desktop

© Copyright 2015 Hewlett Packard Enterprise Development Company, L.P. The information contained herein is subject to change without notice. The only warranties for HPE products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HPE shall not be liable for technical or editorial errors or omissions contained herein.

Trademark acknowledgments, if needed.

Created July 2017